






RECEIVED  
JAN 19 1964  
JAN 19 1964





PRIOR ART



FIGURE 1



PRIOR ART



PRIOR ART



PRIOR ART



CEVHED 35

1964 JAN 1964

0012-10-2810






FIGURE 3






FIGURE 5A




FIGURE 5B




FIGURE 5C








FIGURE 5D



PRIOR ART

FIGURE 6






FIGURE 8



SIGNAL GROUND




FIGURE 10A




FIGURE 10B




FIGURE 10C






FIGURE 10D



PRIOR ART

FIGURE 11



PRIOR ART

FIGURE 12




FIGURE 13



015W101837

1997-10-10

2018-10-10




FIGURE 14




FIGURE 15A



FIGURE 15B




FIGURE 15C






FIGURE 15D



PRIOR ART

FIGURE 16



PRIOR ART

FIGURE 17




FIGURE 18




FIGURE 19




FIGURE 20A




FIGURE 20B




FIGURE 20C






FIGURE 20D



PRIOR ART

FIGURE 21

[illegible]

## PRIOR ART

FIGURE 22




FIGURE 23



FIGURE 24




FIGURE 25A




FIGURE 25B




FIGURE 25C




FIGURE 25D